Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0817/1

Work Order Type: Weatherization

Audit Name: 17017UC-0817

CLIENT INFORMATION

Client ID: 17017UC-0817

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:*

Agency Contact: Carlisle, Ron Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1967 SITE BUILT HOME

Measures

ı	Measure 1 Auto 7	matic Foundation Vent	s 8" x 16'	' X	Componen	its			Inspected
C	comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Construction Materials/Hardwar e	Install Foundation Vents	Each	7					
C	Other Detail						_		
				Measur	e Sub Total:			Sub Total:	
		Ducts UCTS & DUCT REGISTE	ERS W/M/	ASTIC	Component IN KITCHE	N & BATI	- -	Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Duct Sealing	Each	1					
C	Other Detail						,		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

/	<i>Measure</i> 3 Infi	Itration Redctn			Componen	its			Inspected
C	PIPES OUTSI	AULK CROWN MOULD I IN BATH, KITCHEN, & U DE. 4' SHEETROCK REF W/R30 & W/STRIP	JTILITY. C	AULK \	WINDOWS	D11-14 C	N		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
0	ther Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 4 DW	H Pipe Insulation			Componen				Inspected
		H Pipe Insulation			Component Estimated			Actual	Inspected
C		H Pipe Insulation Description / Comment	Units	Qty	•		Qty		Inspected Total
C :	omment	·	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
C :	omment Material / Labor	Description / Comment			Estimated	<u> </u>	Qty	Actual	
# 1	omment Material / Labor	Description / Comment DHW Pipe Insulation			Estimated	<u> </u>	Qty	Actual	
C 4 1 2	omment Material / Labor Insulation	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>	Qty	Actual	
C 4 1 2	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>	Qty	Actual	
C 4 1 2	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>	Qty	Actual	
C 4 1 2	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>		Actual	
# 1 2 O	omment Material / Labor Insulation Labor ther Detail	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# 1 2 O	omment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# 1 2 O	omment Material / Labor Insulation Labor ther Detail	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# 1 2 O	omment Material / Labor Insulation Labor ther Detail	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

	WH Tank Insulation			Componen	ts			Inspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
	R-10 minimum-use bubble wrap							
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Measure 6 Co	O Monitor is Needed			Componen	ts		1	Inspected
	O Monitor is Needed			Componen Estimated			Actual	Inspected
	Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment	Description / Comment	Units Each		Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safe	Description / Comment		Qty	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items	Description / Comment ty 9-volt CO Monitor	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty 9-volt CO Monitor	Each	Qty 1	Estimated		Qty	Actual	Total
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty 9-volt CO Monitor	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty 9-volt CO Monitor	Each Hour	Qty 1 1	Estimated			Actual	
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty 9-volt CO Monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Health and Safe Items 2 Labor Other Detail	Description / Comment ty 9-volt CO Monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 7 Smoke Detector is Needed					Componen	its	Inspected		
C	Comment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	9-volt Smoke Detector	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail						,		
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	